

# Assembly instruction

# Series BNC, TNC, N v8 No.3015

## Tools and materials required:

Stanley blade  
Scissors  
Crimp tool (see table below)



## Straight connectors for flexible cable

Cable entry: SUHNER Full-Crimp


### Connector types: (e. g.)

11 BNC-50-3-4	11 BNC-50-4-4	11 BNC-75-5-6
21 BNC-50-3-2	21 BNC-50-4-1	21 BNC-75-5-3
11 TNC-50-3-9	11 TNC-50-4-7	
21 TNC-50-3-7	21 TNC-50-4-6	
11 N-50-3-28	11 BNC-75-4-4	


This connector is supplied in 3 parts	<b>Suitable cables e. g.:</b>	RG 58 C/U	RG 59 B/U	G 05133 d
	<b>Centre contact:</b>	cavity 2	cavity 2	cavity 2
	<b>Braid:</b>	cavity B	cavity C	cavity 8,0
	<b>Crimp tool:</b>	2B (orange)	2C (yellow)	2/8,0




Slide ferrule A onto cable.  
Prepare cable according to diagram.  
**CAUTION:** Do not damage braid, dielectric and inner conductor of cable!



Push contact B over inner conductor of cable to abut dielectric and crimp.



Splay out braid and insert cable in connector body C.  
Ensure that braid lies above the crimp neck.



Slide ferrule A over braid and crimp as close to connector body C as possible.



SUHNER's skilled staff and specialised equipment are available to carry out complete R. F. lead-assembly on your behalf. We mount your connectors on cables at economic prices! Please contact our representative for further details of this service.



**HUBER+SUHNER LTD. CH-9100 HERISAU**

Deutscher Text: siehe Rückseite